

TP1-Turning

Bracket: button


Objectives: generate an iso NC program from a simple part of revolution

procedure :


- open file: button

Creation of the raw part and the machining profilesblank

- create a new part body by clicking on Insert>part bodypiece- rename the "stock and contour" part body (property >property-element trees)- open a sketch in the YZ plane- build the rough contour as in the figure (with aextra thickness at the end of 2mm)- make a part of revolution from this sketch.- set the transparency properties of the raw part (set to 200)- make the sketch visible.




Relief point- open a sketch in the YZ plane- construct a point as in the figure as in the figure- make the sketch visible.



Creating the chuck-part assembly

- open a new assembly- rename it "button_ph30"- insert the chuck- insert button- constrain it as in the figure- make a backup of the assembly



Creation of the machining phase

- open the workshop by clicking on



or Start>NC Manufacturing> Lathe Machining

Declaration of the geometries used for the simulation

double click



Phase d'usinage.1

in the tree.

workpiece geometry

click on



the dialog box disappears

click in the tree on: Main body of the button

double click outside to validate the selection

blank geometry

click on



the dialog box disappears

click in the tree on: the "raw and outline" body of the button

double click outside to validate the selection

machining fixture geometry

click on



the dialog box disappears

click in the tree on: the chuck


double click outside to validate the selection

machining mark

click on the icon



click on one of the red areas to declare the marker
click on the mark
validate by clicking on OK



choice of machine

click on the icon



adjust the parameters corresponding to the menu below
against


Catalog of tools:

- click on the tab

Changement d'outil

- choose the catalog: tooltowers

validate by clicking on OK



tool change position

click on the tab



adjust the parameters corresponding to the menu opposite

confirm by clicking on OK to close the machining phase window

- make a backup under the name "bouton_ph30"


Creation of operations

Ebauche

Click Insert>Machining Operations>Rough Turning

then click on manufacturing program.1 in the tree.

the following menu appears




Choice of tool

click on




- set tool number to 2



Choice of tool body

click on




- click on  to choose the tool body from the catalog

"lathe tools"- choose tool

T2_Ext_55°_G- click

OK

Choice of insert



- click on



- click on



to choose the insert from the "turning tools" catalog

- click on



- choose the 55° insert

- click OK

Declaration of contour geometries

- click on



the following menu appears
Outline of the blank

- click on the red area marked "gross"-
click on one end of the raw contour- click
OK

Part outline- click on the red area
marked "room"- click on one end of the
part outline- click OK

- adjust the part oversize: 0.5 mm

Machining strategy

- click on



the following menu appears- set roughing mode to
parallel contour- set the axial cutting depth to: 0.5
mm- set the radial cutting depth to: 2 mm

Approach and withdrawal of tools

click on





- check the approach box

- click on



the following menu appears- click on the point
identified by the arrowthe window disappears- click
on the sketched point in the "raw and outline"
bodythe window reappears- check the withdrawal
box



- click on



the following menu appears- click on the point identified by the arrow the window disappears- click on the sketched point in the "raw and outline" body the window reappears

cutting condition

- click on



the following menu appears

- complete the speed as on the table



Simulation


- click on




- follow the procedure described in the milling tutorials- click OK to exit the simulation- click on OK to validate the simulation

profile finish

- Click on Insert>Turning Operations>Profile Finish



- click on the red area- click on the marked entities of 1,2 and 4 (be careful not to click on one end of the segments)- click OK



cutting condition

- click on



the following menu appears

- complete the speed as on the table

Vitesse d'avance	
Engagement:	0,3mm_turn
Usinage:	0,05mm_turn
Chamfreinage:	0,3mm_turn
Dégagement:	0,8mm_turn
Vitesse de broche	
Usinage:	2500turn_mn
Unité:	Angulaire

Machining strategy

- click on



the following menu appears

- complete the parameters as opposite

Orientation:	Externe
Localisation:	Avant
Direction d'avance:	Pers droite
Contournage des coins extérieurs:	Angulaire
<input type="checkbox"/> Défonçage	
<input type="checkbox"/> Usinage en dessous de l'axe broche	
CUTCOM:	Out
Compensation d'outil	# 3

Approach and withdrawal of tools

Same as for the draft

Simulation

- click on




- follow the procedure described in the milling tutorials-
click OK to exit the simulation- click on OK to validate
the simulation


Create punch and drill operations

same procedure as in the milling tutorials

choice of tools



Vitesse d'avance	
Approche:	10mm_turn Rapide
Plongée:	0,5mm_turn Rapide
Usinage:	0,2mm_turn
Retrait:	0,5mm_turn Rapide
Unité:	Angulaire
Vitesse de broche	
Sortie vitesse	
Usinage:	3000turn_mn
Unité:	Angulaire



NC code generationsame procedure as for
the milling tutorialsChoose the
workstation:Establish Part Process: Cap 2