



TP4

Support: phase 20 vice base



procedure:

- open the assembly : `sole_ph20_montage_complet` -
- hide the machined base ph10 - Insert the "machined base" giving it the same constraints as the raw base. save the assembly under the name "`montage_semelle_ph20_complet`"



assembly tree "montage_semelle_ph20_complet"

phase 20 sole range

