


TP2

Support: strap operating lever

Objectives: drawing the unfolded part

procedure :

Extract Drawings from the Sheet Metal Part The sheet metal part is displayed.

Click or select  **File->New...>drawing**

The Drafting workshop is launched. Select **A3ISO** landscape and click **OKAY**.

The drawing sheet appears.
Tile windows horizontally.

Select the Flat View icon from the  drawing toolbar.

This icon is added to the drawing toolbar provided that the Sheet Metal Part Design Workbench is present.

Choose the **xy-plane** in the sheet metal specification tree. The unfolded view is displayed with the axes and the limits of the bends. The drawing sheet should look like this:

